





PHONE
Art. 8870




MAINS



NOTICE

The power connections from the transformer MUST be a separate cable to the handset cable. If the power is routed in the same cable as the handset connections, audio hum will be heard when the phone is in use.



Please note that all drawings and diagrams supplied for bespoke applications for RSS products are given as a free service to assist customers and no liability for errors and omissions can be accepted by RSS. Customers remain entirely responsible for the quality and correctness of all installation work.

ISS	DESCRIPTION	DATE	ELVOX	TITLE	DRAWN	CHECKED	APPROVED	DATE
1	INITIAL	16 - 01 - 12				1 Way Audio AC Call Kit	MH	
					DRAWING No. RSS 2000/120b			